



SBI-521 Packing List

Note: Before assembly the scale, please carefully check the below parts list.

Parts list

1. Indicator with built-in power supply x 1
2. Sealing wire x 1
3. Sealing block x 1

Manuals

1. User manual x 1
2. Safety sheet x 1
3. Battery warning x 1



SBI-521 Packing List

Note: Before assembly the scale, please carefully check the below parts list.

Parts list

1. Indicator with built-in power supply x 1
2. Sealing wire x 1
3. Sealing block x 1

Manuals

1. User manual x 1
2. Safety sheet x 1
3. Battery warning x 1



FI-521 Packing List

Note: Before assembly the scale, please carefully check the below parts list.

Parts list

1. Indicator x 1
2. Sealing wire x 1
3. Sealing block x 1

Manuals

1. User Manual x 1
2. Capacity label x 1



FI-521 Packing List

Note: Before assembly the scale, please carefully check the below parts list.

Parts list

1. Indicator x 1
2. Sealing wire x 1
3. Sealing block x 1

Manuals

1. User Manual x 1
2. Capacity label x 1